ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0538, W0534	1st Main Rd, 2nd Crs	Thanisandra
Segment No.	**Total Length (m)**	
6/C-W0538/S061705	77.03	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	77.03	77.634970	13.056760	77.635501	13.056507	Thanisandra A.K. Colony main road	Dead end road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads, drains at Thanisandra in ward no. 06 Byatarayanapura sub division	2000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		006-15-000004
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/107/2018-19	07/09/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/10/2018	27/10/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V. Chandrappa		0.00
Phone No.	**E-Mail ID**	
9448447181		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh

Date of Inspection	Remarks
13/11/2018	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark